Oil Field Environmental Incident Summary

Responsible Party: CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: VIBE 1-26H1

Field Name: LEAF MOUNTAIN Well File #: 25799

Date Incident:10/16/2014Time Incident:09:40Facility ID Number:County:BURKETwp:161Rng:94Sec:23Qtr:

Location Description:

Submitted By: Timothy lise Received By:

Contact Person: Timothy Ilse

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: Yes

Spilled Units Recovered Units Followup Units

Oil

Brine 30 Barrels 30 Barrels 30 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 10/14/2016 Clean Up Concluded: 10/17/2014

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

Well site soil

Action Taken or Planned:

Standing fluid was sucked up and contaminated soil will be removed and disposed of.

Wastes Disposal Location: Prairie Disposal

Agencies Involved: Called BobGrarbe at 2:40 am

Updates

Date: 10/18/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, remained on location according to the report. NDIC retains oversight.